## GOODWE





#### Ultra-lightweight

- The lightest weighs 5.6 kg/m²
- Up to 60% lighter than conventional module
- · Suitable for roofs with a low load-bearing capacity



### High Reliability

- Wind<sup>1</sup> and hail<sup>2</sup> impact resistance
- Maximum static snow load up to 2400Pa
- · Enhanced capability for self-cleaning
- PPO Edge protection
- · Reduced fire risks

<sup>1</sup>Third-party lab test from CTC <sup>2</sup>Third-party TUV lab: report number CN22Z6P8 001



#### Various & Quick Installation

- No roof penetration
- 3 Min/pcs rapid installation
- · Clamps for metal roofs
- Glue for flat roofs




### High Power Generation


- High-efficiency TOPCon cells
- 2% less generation loss<sup>3</sup> with ventilation design
- Up to 214W per square meter of power generation

<sup>3</sup>Based on internal lab test









Structural Data	BMT-G4/108A
Size	2275±2*905±2*5±1mm
Weight	11.5±0.8kg
Unit Weight	5.6±0.4kg/m²
Front Surface	1.6mm tempered glass
Cell Type	N-Type TOPCon Half Cells (108pcs)
Frame	Frameless*

#### **Electrical Data (STC)**


Max Power (Pmax)	440W
Power/m² (W/m²)	214W/m <sup>2</sup>
Efficiency (%)	21.4%
Voltage at Max Power (Vmpp)	33.26V
Voltage at Open Circuit (Voc)	39.32V
Current at Max Power (Impp)	13.23A
Current at Short Circuit (Isc)	13.9A

#### **Load Capacity**

Maximum static load on the front	2400Pa
Maximum static load on rear side	2400Pa

# 30-year power generation performance guarantee

- 1% degradation in the first year
- 2 12-year product warranty
- **0.4%** decay per year
- 30-year power guarantee



#### **Working Parameters**

Maximum System Voltage	1500V
Maximum Fuse Rating Operation	25A
Temperature Range	-40° C ~+85° C
Hail Test	Hail diameter: 25mm Specified speed: 23m/s
The Rated Operating Temperature	45±2℃
Fire-resistant Class	С
Ingress Protection Rating	IP67
Protection Class	II

#### **Temperature Parameters**

Isc TP	+0.029%/°C
Voc TP	-0.27%/°C
Pmp TP	-0.30%/°C

\*With PPO edge protection to reduce the risk of glass damage from corner impacts.



